



MxP	A	E	B
2x0.4	3.8	2	1.5
2.5x0.45	4.5	2.5	2
2.6x0.45	4.5	2.6	2
3x0.5	5.5	3	2.5
4x0.7	7	4	3
5x0.8	8.5	5	4
6x1.0	10	6	5
8x1.25	13	8	6
10x1.5	16	10	8
12x1.75	18	12	10

Part Number	Type	M-	L	ℓ
CB 2-	Studs - Fully Threaded	4		
		5		
		6		
		8		
		10		
		12		
CB 2.5-	Studs - Fully Threaded	4		
		5		
		6		
		8		
		10		
		12		
CB 2.6-	Studs - Fully Threaded	4		
		5		
		6		
		8		
		10		
		12		
CB 3-	Studs - Fully Threaded	5		
		6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
CB 3-	Studs - Fully Threaded	18		
		25		
		30		
		35		
		40		
		45		
		50		
		55		

Part Number	Type	M-	L	ℓ
CB 4-	Studs - Fully Threaded	5		
		6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
CB 5-	Studs - Fully Threaded	5		
		6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
CB 5-	Studs - Fully Threaded	22		
		25		
		30		
		35		
		40		
		45		
		50		
		55		
		60		

Part Number	Type	M-	L	ℓ
CB 6-	Studs - Fully Threaded	6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
		25		
CB 6-	Studs - Fully Threaded	24		
		30		
		35		
		40		
		45		
		50		
		55		
		60		
		65		
		70		
		75		
CB 6-	Studs - Fully Threaded	80		
		85		
		90		
		95		

Part Number	Type	M-	L	ℓ
CB 8-	Studs - Fully Threaded	8		
		10		
		12		
		15		
		16		
		18		
		20		
		22		
		25		
		30		
		35		
CB 8-	Studs - Fully Threaded	28		
		40		
		45		
		50		
		55		
		60		
		65		
		70		
		75		

Part Number	Type	M-	L	ℓ
CB 10-	Studs - Fully Threaded	10		
		12		
		15		
		20		
		25		
		30		
		35		
		40		
		45		
		50		
		55		
CB 10-	Studs - Fully Threaded	32		
		60		
		65		
		70		

Part Number	Type	M-	L	ℓ
CB 12-	Studs - Fully Threaded	15		
		20		
		25		
		30		
		35		
		40		
		45		
		*50		



Type M - L

CB 3 - 20