



MxP	A	E	B
2x0.4	3.8	2	1.5
2.5x0.45	4.5	2.5	2
2.6x0.45	4.5	2.6	2
3x0.5	5.5	3	2.5
4x0.7	7	4	3
5x0.8	8.5	5	4
6x1.0	10	6	5
8x1.25	13	8	6
10x1.5	16	10	8
12x1.75	18	12	10

Part Number	Type	M-	L	ℓ
CB 2-	Studs - Fully Threaded	2-	4	
		5		
		6		
		8		
		10		
		12		
CB 2.5-	Studs - Fully Threaded	2.5-	4	
		5		
		6		
		8		
		10		
		12		
CB 2.6-	Studs - Fully Threaded	2.6-	4	
		5		
		6		
		8		
		10		
		12		
CB 3-	Studs - Fully Threaded	3-	5	18
		6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
CB 4-	Studs - Fully Threaded	4-	5	20
		6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
CB 5-	Studs - Fully Threaded	5-	5	22
		6		
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
CB 6-	Studs - Fully Threaded	6-	6	24
		8		
		10		
		12		
		14		
		15		
		16		
		18		
		20		
		22		
		25		
CB 8-	Studs - Fully Threaded	8-	8	28
		10		
		12		
		15		
		16		
		18		
		20		
		22		
		25		
		30		
		35		
CB 10-	Studs - Fully Threaded	10-	10	32
		12		
		15		
		20		
		25		
		30		
		35		
		40		
		45		
		50		
		55		
CB 12-	Studs - Fully Threaded	12-	15	*50
		20		
		25		
		30		
		35		
		40		
		45		
		50		
		55		
		60		
		65		

Part Number	Type	M-	L	ℓ			
CB 2-	Studs - Fully Threaded	2-	4				
		5					
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
CB 2.5-	Studs - Fully Threaded	2.5-	4				
		5					
		6					
		8					
		10					
		12					
		15					
		CB 2.6-	Studs - Fully Threaded		2.6-	4	
					5		
					6		
					8		
10							
12							
15							
CB 3-	Studs - Fully Threaded			3-	5	18	
				6			
				8			
				10			
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 4-	Studs - Fully Threaded	4-	5	20			
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 5-	Studs - Fully Threaded	5-	5	22			
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 6-	Studs - Fully Threaded	6-	6	24			
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
		25					
CB 8-	Studs - Fully Threaded	8-	8	28			
		10					
		12					
		15					
		16					
		18					
		20					
		22					
		25					
		30					
		35					
CB 10-	Studs - Fully Threaded	10-	10	32			
		12					
		15					
		20					
		25					
		30					
		35					
		40					
		45					
		50					
		55					
CB 12-	Studs - Fully Threaded	12-	15	*50			
		20					
		25					
		30					
		35					
		40					
		45					
		50					
		55					
		60					
		65					

Part Number	Type	M-	L	ℓ			
CB 2-	Studs - Fully Threaded	2-	4				
		5					
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
CB 2.5-	Studs - Fully Threaded	2.5-	4				
		5					
		6					
		8					
		10					
		12					
		15					
		CB 2.6-	Studs - Fully Threaded		2.6-	4	
					5		
					6		
					8		
10							
12							
15							
CB 3-	Studs - Fully Threaded			3-	5	18	
				6			
				8			
				10			
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 4-	Studs - Fully Threaded	4-	5	20			
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 5-	Studs - Fully Threaded	5-	5	22			
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 6-	Studs - Fully Threaded	6-	6	24			
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
		25					
CB 8-	Studs - Fully Threaded	8-	8	28			
		10					
		12					
		15					
		16					
		18					
		20					
		22					
		25					
		30					
		35					
CB 10-	Studs - Fully Threaded	10-	10	32			
		12					
		15					
		20					
		25					
		30					
		35					
		40					
		45					
		50					
		55					
CB 12-	Studs - Fully Threaded	12-	15	*50			
		20					
		25					
		30					
		35					
		40					
		45					
		50					
		55					
		60					
		65					

Part Number	Type	M-	L	ℓ			
CB 2-	Studs - Fully Threaded	2-	4				
		5					
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
CB 2.5-	Studs - Fully Threaded	2.5-	4				
		5					
		6					
		8					
		10					
		12					
		15					
		CB 2.6-	Studs - Fully Threaded		2.6-	4	
					5		
					6		
					8		
10							
12							
15							
CB 3-	Studs - Fully Threaded			3-	5	18	
				6			
				8			
				10			
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 4-	Studs - Fully Threaded	4-	5	20			
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 5-	Studs - Fully Threaded	5-	5	22			
		6					
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
CB 6-	Studs - Fully Threaded	6-	6	24			
		8					
		10					
		12					
		14					
		15					
		16					
		18					
		20					
		22					
		25					
CB 8-	Studs - Fully Threaded	8-	8	28			
		10					
		12					
		15					
		16					
		18					
		20					
		22					
		25					
		30					
		35					
CB 10-	Studs - Fully Threaded	10-	10	32			
		12					
		15					
		20					
		25					
		30					
		35					
		40					
		45					
		50					
		55					
CB 12-	Studs - Fully Threaded	12-	15	*50			
		20					
		25					
		30					
		35					
		40					
		45					
		50					
		55					
		60					
		65					



Type M - L  
CB 3 - 20